

## Elastomeric N95 / P100 Reusable Respirator WITHOUT an Exhalation Valve



## Sizing Guide










This guide will assist in selecting the correct respirator size for your face.

Begin with measuring the vertical line as shown to determine the dimension between the nose-bridge area to the chin.


## **Vertical Line Measurement**



Once you determine the vertical dimension, measure the horizontal line. In order to obtain a proper fit and airtight seal, your measurements cannot be greater than the dimensions shown below. Refer to images below of interior of the Comfort-Air®NxMD respirators.



400NxMD Small / Medium Vertical Line - 3.75" Horizontal Line - 4.55"



400NxMD Medium / Large Vertical Line - 4.5" Horizontal Line - 3.75"

Scan to Buy

